



**Exam** : HP HP0-S16

**Title** : Implementing HP Bladesystem

**Update** : Demo

1. Which HP offering provides individual services such as image loading, asset tagging and custom packaging for customers?


- A.Factory Express
- B.HP Support Plus
- C.HP Support Services
- D.HP Care Pack Services

**Answer: A**


2. Click Next or More to continue.

Click the Task button.

Click the HP Virtual Connect Ethernet module.



**Answer:**



3. Which processor uses 64-bit x86-based standard architecture and Hyper-Transport technology?

- A.AMD Athlon
- B.Intel Itanium2
- C.AMD Opteron
- D.Intel Xeon 7000 Sequence

**Answer: C**

4. What causes a system to perform an ASR (Automated System Recovery)?

- A.A hardware failure occurs on a redundant hardware option.
- B.A hardware failure occurs on a non-redundant hardware option.
- C.The ASR timer expires due to the operating system not responding.
- D.The ASR monitor determines that the operating system wrote to a bad memory location.

**Answer: C**

5. Which memory protection technology protects against multiple, non-correctable multi-bit errors with no performance degradation?

- A.RAID memory
- B.Online spare memory
- C.Advanced ECC memory
- D.Single-board mirrored memory

**Answer: D**

6. What are advantages of using point-to-point storage technology with Serial Attached SCSI (SAS)? (Select two.)

- A.greater disk capacity
- B.increased bandwidth
- C.higher fault tolerance of the disks
- D.better isolation of hard drive failures

**Answer: BD**

7. Which options are available when you enable HP NIC teaming? (Select two.)

- A.fault tolerance
- B.shortest path routing
- C.physical stack balancing
- D.NIC assisted load balancing
- E.switch assisted load balancing

**Answer: AE**

8. Which c-Class server blades support Fully Buffered-DIMM Memory? (Select two.)

- A.BL460c
- B.BL465c
- C.BL480c
- D.BL685c

E.BL860c

**Answer:** AC

9. Which server management products are part of ProLiant Essentials? (Select three.)

A.Insight Power Manager

B.Rapid Deployment Pack

C.Instant Support Enterprise Edition

D.StorageWorks Management Pack

E.Virtual Machine Management Pack

**Answer:** ABE

10. Click the Task button.

Click on the server blade in the c3000 enclosure that has a minor warning

Tools ▾ Deploy ▾ Configure ▾ Diagnose ▾ Reports ▾ Tasks & Logs ▾ Options ▾ Help ▾ Debug ▾

## UserDefinedRack (Rack)

View as:

Select:  All Blades  All Interconnect Switches  All Onboard Administrators  All Enclosures

**UserDefinedRack (42U)**

Data Center ID:	XXX	Data Center Location:	YYY
Row Number:	1	Position in Row:	1

**9781-c3000 (37U - 42U)**

Front View	Rear View	Enclosure Name	9781-c3000
		Serial Number	MONTERO001
		UUID	09MONTERO001
		Unit ID (LED)	ON
		Onboard Administrator	c3000-0a
		Health Status	<span style="color: orange;">▼</span>
		Power Redundancy	Non Redundant
		Fan Redundancy	Redundant

**Encl\_c/00011 (27U - 36U)**

Front View	Rear View	Enclosure Name	Encl_c700011
		Serial Number	USE6281EK9
		UUID	06USE6281BK9
		Unit ID (LED)	OFF
		Onboard Administrator	ca-0016355e36e4

Done

Answer:

Tools ▾ Deploy ▾ Configure ▾ Diagnose ▾ Reports ▾ Tasks & Logs ▾ Options ▾ Help ▾ Debug ▾

## UserDefinedRack (Rack)

View as: picture ▾

Select:  All Blades  All Interconnect Switches  All Onboard Administrators  All Enclosures

**UserDefinedRack (42U)**

Data Center ID:	XXX	Data Center Location:	YYY
Row Number:	1	Position in Row:	1

**9781-c3000 (37U - 42U)**

Front View	Rear View	Enclosure Name	9781-c3000
		Serial Number	MONTERO001
		UUID	09MONTERO001
		Unit ID (LED)	ON
		Onboard Administrator	c3000-0a
		Health Status	<span style="color: orange;">▼</span>
		Power Redundancy	Non-Redundant
		Fan Redundancy	Redundant

**Encl\_c/00011 (27U - 36U)**

Front View	Rear View	Enclosure Name	Encl_c700011
		Serial Number	USE6281EK9
		UUID	06USE6281BK9
		Unit ID (LED)	OFF
		Onboard Administrator	ca-3016355e36e4

Done

This document was created with Win2PDF available at <http://www.win2pdf.com>.  
The unregistered version of Win2PDF is for evaluation or non-commercial use only.  
This page will not be added after purchasing Win2PDF.

